


410.59.41**Reparo da Bomba CAV Perkins 6357**


Retentor para eixo de Ø 28,0 x 38,0



Ref.: 905941A

410.59.52**Reparo da Bomba CAV Perkins 6358**


Retentor para eixo de Ø 22,0 x 34,0




Ref.: 9059/52

410.51.24**Reparo da Bomba CAV DPS Perkins 1006-6T/6W com Retentores**

Retentor para eixo de Ø 20,0 x 35,0



Ref.: 7135-124

410.51.26
Reparo da Bomba CAV DPS FNH Perkins 1006-T

410.90.08
Reparo Parcial do Regulador da Bomba CAV


410.90.13
Reparo da Bomba CAV DPC

Retentor para eixo de Ø 28,0 x 38,0




Reparo da Bomba DP100

Retentor para eixo de Ø 22,0 x 34,0



Ref.: 9059-052A

Reparo da Bomba CAV Perkins 4236/6357/6358



Ref.: 9059-19A